



Boat Repair Portfolio

Viking 22

Hull and Deck Paint Work



Viking 22: Hull and Deck Paint Work

Deck Progress Photos



Hull Progress Photos





Viking 22

Hull and Deck Work Finished

C&C 40
Hull Repaint




Sand Blasting



Interprotect Barrier Coat



Antifoul Bottom Paint



O Day 30

Rudder Repair

Before



Cut Open



Cut Open Cross Section



Cut Out Core



Fiberglass



New Core



New Fiberglass



Microballoons



Interprotect

